



File Path: S:\06 Technical Documents\034 START R3\0323\_08\_002\Figure7 BrineSolids.mxd  
 Date Saved: 04/25/24



▲ Brine Solid Sample

▭ Zones

Brine Solid Samples are Processed  
 Solids such as Salt, Filter Cake, and Debris. These are not Soil Samples.

Source: Esri, HERE, Garmin, (c) OpenStreetMap contributors, and the GIS user community  
 Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community  
 EPA Contract No: 68-HF-0320-00003 TD No: T601-23-06-003

Fairmont Brine Radiological Sampling Event  
 Fairmont, Marion County, West Virginia

**Figure 6**  
**Brine Solid Sample Locations**



Prepared For: EPA R3 START VI  
 Coordinate System: NAD 1983 2011 StatePlane West Virginia North Zone 1 FIPS 5003